Setup Certags - ComplyPro Label Printer without using ComplyPro Label Designer

Step 1:

Please install driver from the following source:

Global / USA	https://www.certags.com/download-links
UK / Europe	https://certags.co.uk/label-printers/complypro-down-loads/
Australia / NZ	https://certags.com.au/label-printers/complypro-down-loads/
Germany	https://certags.de/downloads/

Step 2:

Windows 7	Left click the Windows symbol on the bottom left corner, select "Devices and Printers".
Windows 10	Right click on the Windows symbol on the bottom left corner, click on Settings -> Devices -> Printers & Scanners. Here you can see the printer „BP530".

Step 3:

Click on BP530 and click "Manage" then click "Printer properties".

Select the Tab "Tools" and click on "Driver Options".

Select the tab "Regional Options" and select "Millimeter" on the bottom drop down menu.

Confirm both windows with OK.

Step 4:

Next click on "Printing preferences".

Step 5:

Select the tab "Page Setup" and click "Edit" on top.

Step 6:

Put in your label size and click OK.

Important: For Heavy Duty Clear Wrap and Economy Clear Wraps please enter **width 40 mm and height 50 mm.**

Step 7:

Please click on tab "Stock".

Uncheck both check marks and set the settings as follows:

Vinyl Tape

Heavy Duty Clear Wrap / Economy Clear Wrap

Gap length:
Total length minus 50 mm.
(e.g. for 200 mm HDCW type in 150 mm)

Step 8:

Select tab "Options" and uncheck both check marks.

Please select speed 50.80 mm/s on top and below you slide the slider to 16.

Step 9:

Click on Apply and then OK.

Die Cut PVC Labels